Date of issue: 7.12.18 NZ Safety Data Sheet

### 1. Identification of the Substance/Mixture and Supplier.

Product name: 408 DECK & FURNITURE OIL

Application: Wood oil

Company: DECORA GROUP LTD

7 Akatea Road, Glendene, Auckland, New Zealand.

 Telephone:
 09 818 9215

 Facsimile:
 09 818 7862

 Emergency telephone:
 0800 761 333

National Poisons Centre Tel: 0800 764766 (0800 POISON)

### 2. Hazards Identification.

HSNO Status: Classified as hazardous according to the criteria of HSNO. HSNO approval number

HSR002662

**DG Status:** Classified as Dangerous Goods according to NZS5433

Signal Word: WARNING

HAZARD CLASSIFICATIONS HSNO		HAZARD STATEMENTS		
3.1C		H226 Flammable liquid and vapour.		
6.3B		H316 Causes mild skin irritation.	N/A	
6.4A		H319 Causes serious eye irritation.		
6.5B		H317 May cause an allergic skin reaction.		
6.8B		H361 Suspected of damaging fertility or the unborn child.		
6.9B (repeat exposure)		H373 May cause damage to organs through prolonged or repeated exposure.		
9.1B		H411 Toxic to aquatic life with long lasting effects.		
DDEVENTIO	N STATEMENTS			
P103	Read label before use			
P201		Obtain special instructions before use.		
P202		Do not handle until all safety precautions have been read and understood.		
P210		Keep away from heat/sparks/open flames/hot surfaces. No smoking.		
P233		Keep container tightly closed.		
P240		Ground/bond container and receiving equipment.		
P241		Use explosion-proof electrical/ventilating/lighting equipment.		
P242		Use only non-sparking tools.		
P243		Take precautionary measures against static discharge.		
P260		Do not breathe mist/vapours/spray.		
P264		Wash thoroughly after handling.		
P272		Contaminated work clothing should not be allowed out of the workplace.		
P273	Avoid release to the environment.			

Date of issue:	7 12 10		N7 Sefety Data Sheet		
P280	7.12.18 NZ Safety Data Sheet  Wear protective gloves/protective clothing/eye protection/face protection.				
P281	Use personal protective equipment as required.				
F201	Use personal protective equipment as required.				
RESPONSE ST	ATEMEN	TS			
P370 + P378	In case of fire: Use foam, carbon dioxide or dry chemical powder for extinction.				
	sact co. coo loan, salbon dionido of dry offerfical powder for extinction.				
P308 + P313	IF expos	ed or concerr	ned: Get medical advice/	attention.	
P314		et medical advice/attention if you feel unwell.			
P303 + P361	IF ON SI	ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin			
+ P353		h water/shower.			
P302 + P352		N SKIN: Wash with plenty of soap and water.			
P333 + P313	1		occurs: Get medical ad	vice/attentior	า.
P363			othing before reuse.		
P305 + P351				everal minute	s. Remove contact lenses, if
+ P338			o. Continue rinsing.		
P337 + P313	If eye irri	tation persists	s: Get medical advice/at	tention.	
P391	Collect s	pillage.			
OTODA OF OTA	TENAENIT				
STORAGE STA P403 + P235					
			ed place. Keep cool.		
P405	Store loc	кеа ир.			
DISPOSAL STA	TEMENT	9			
P501		Section 13.			
F 301	TABLET TO A	Section 13.			
		ormation on			
Chemical Entit			CAS Number		Proportion %w/w
White Spirits – I	High Flash		Blend		30 - <60
Tung Oil			8001-20-5		10 - <30
Gum Turpentine			8006-64-2		1 - <10
Naphtha, petrole	eum, heav	У	64742-82-1		1 - <10
Biocide			Blend		1 - <5
Xylene			1330-20-7		0.1 - <1
Balance of ingredients: Non-hazardous, or below the hazardous threshold.					
4. First Ai	d Measur	es.			
Swallowed		If swallowed	ved do NOT induce vomiting. Give water to drink. Get medical attention if s occur.		
Inhaled		If inhaled, move the victim to fresh air immediately. Begin artificial respiration if			
		breathing has stopped. Obtain medical attention if symptoms occur.			
Eye Contact		If splashed in the eyes, wash out immediately with water. Obtain medical attention			
-		if irritation occurs.			
		If skin or hair contact occurs, remove contaminated clothing and flush skin and			
		hair with running water. Get medical attention if symptoms occur.			
			contact the National Poisons Centre – 0800 POISON (0800 764 766) –		
	or a doctor, immediately.				
5. Fire-Fig	ghting Me	asures.			
Suitable exting media	juishing	In case of fi	re, use water spray (fog)	, foam, dry c	hemical or CO2.
Unsuitable		High volume	e water jet.		
extinguishing i	media				
Hazards from t		In a fire or if	heated, a pressure incr	ease will occ	ur and the container may burst.
· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·		

cubatanaa	NZ Safety Data Sheet		
substance			
Hazardous	Decomposition products may include:		
combustion products	Carbon oxides, Nitrogen oxides, Other noxious substances.		
Special precautions	Promptly isolate the scene by removing all persons from the vicinity of the incident		
for fire-fighters	if there is a fire. No action shall be taken involving any personal risk or without		
	suitable training.		
Special protective	Fire-fighters should wear appropriate protective equipment and self-contained		
equipment for fire	breathing apparatus (SCBA) with a full face-piece operated in positive pressure		
fighters	mode.		
6. Accidental Rele	ase Measures.		
Personal precautions	Wear appropriate Personal Protective Equipment (see section 8). Provide adequate ventilation.		
Environmental	Avoid dispersal of spilt material and runoff and contact with soil, waterways, drain		
precautions	and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).		
Small spill	Stop leak if without risk. Move containers from spill area. Absorb with an inert dry		
	material and place in an appropriate waste disposal container. Eliminate all		
	ignition sources. Use spark-proof tools and explosion-proof equipment. Dispose		
1	via a licensed waste disposal contractor.		
Large spill	Stop leak if without risk. Move containers from spill area. Prevent entry into		
	sewers, water courses, basements or confined areas. Contain and collect spillag		
	with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local		
	regulations (see section 13). Eliminate all ignition sources. Use spark-proof tools		
	and explosion-proof equipment. Dispose of via a licensed waste disposal		
	contractor. Contaminated absorbent material may pose the same hazard as the		
	spilt product.		
7. Handling and Storage.			
Handling	Wear appropriate PPE, and ensure there is adequate ventilation and extraction in		
	the work area. Avoid skin or eye contact, or breathing in the product. Follow		
	precautions listed in section 2 for handling flammable/combustible liquids.		
_	Keep container dry and tightly closed, in a cool, well-ventilated area, away from		
Storage			
Storage	direct sunlight. Keep away from heat, sparks and open flame.		
-			
-	direct sunlight. Keep away from heat, sparks and open flame.		
8. Exposure Contr  Exposure Standards  No exposure limits set for	direct sunlight. Keep away from heat, sparks and open flame.  rol/Personal Protection  r the finished product. Listed components below.		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient	r the finished product. Listed components below.  WES/TWA  WES/STEL  Reference		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)	r the finished product. Listed components below.  WES/TWA WES/STEL Reference 100ppm, 553mg/m3 - NZ-WES		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient	r the finished product. Listed components below.  WES/TWA  WES/STEL  Reference		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene	r the finished product. Listed components below.  WES/TWA WES/STEL Reference 100ppm, 553mg/m3 - NZ-WES 50ppm, 217mg/m3 - NZ-WES		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)	r the finished product. Listed components below.  WES/TWA WES/STEL Reference 100ppm, 553mg/m3 - NZ-WES 50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene	r the finished product. Listed components below.  WES/TWA WES/STEL Reference 100ppm, 553mg/m3 - NZ-WES 50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour concentrations below WES/TWA. Ventilation equipment should be explosion-pro		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene  Engineering Controls	r the finished product. Listed components below.  WES/TWA WES/STEL Reference 100ppm, 553mg/m3 - NZ-WES 50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene  Engineering Controls  Personal Protection	direct sunlight. Keep away from heat, sparks and open flame.  rol/Personal Protection  r the finished product. Listed components below.  WES/TWA WES/STEL Reference  100ppm, 553mg/m3 - NZ-WES  50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour concentrations below WES/TWA. Ventilation equipment should be explosion-prowhen operating in flammable zones.		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene  Engineering Controls  Personal Protection  Respiratory	direct sunlight. Keep away from heat, sparks and open flame.  rol/Personal Protection  r the finished product. Listed components below.  WES/TWA WES/STEL Reference  100ppm, 553mg/m3 - NZ-WES  50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour concentrations below WES/TWA. Ventilation equipment should be explosion-prowhen operating in flammable zones.  Wear a vapour respirator.		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene  Engineering Controls  Personal Protection  Respiratory  Eyes	direct sunlight. Keep away from heat, sparks and open flame.  rol/Personal Protection  r the finished product. Listed components below.  WES/TWA WES/STEL Reference  100ppm, 553mg/m3 - NZ-WES  50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour concentrations below WES/TWA. Ventilation equipment should be explosion-prowhen operating in flammable zones.  Wear a vapour respirator.  Wear chemical goggles.		
8. Exposure Contr  Exposure Standards  No exposure limits set for  Product/Ingredient  Turpentine (wood)  Xylene  Engineering Controls  Personal Protection  Respiratory	direct sunlight. Keep away from heat, sparks and open flame.  rol/Personal Protection  r the finished product. Listed components below.  WES/TWA WES/STEL Reference  100ppm, 553mg/m3 - NZ-WES  50ppm, 217mg/m3 - NZ-WES  General ventilation and local exhaust should be suitable to keep vapour concentrations below WES/TWA. Ventilation equipment should be explosion-prowhen operating in flammable zones.  Wear a vapour respirator.		

Date of issue: 7.12.18 NZ Safety Data Sheet



## 9. Physical and Chemical Properties

PROPERTY	SPECIFICATION
Appearance (physical state, colour,	Liquid, various colours
etc.)	
Odour	Hydrocarbon
Odour threshold	Not available
pH	Not applicable
Melting point/freezing point	Not available
Initial boiling point and boiling range	Est. ~147°C
Flash point	Est. ~31°C
Flammability (solid, gas)	Not applicable
Upper/lower flammability or explosive limits	Vapours may form explosive mixtures with air
Vapour pressure	Not available
Vapour density	Not available
Relative density	0.83 – 0.85
Solubility	Not soluble in water
Partition coefficient: n-octanol/water	Not available
Auto-ignition temperature	Not available
Decomposition temperature	Not available
Viscosity	20-25 cP

## 10. Stability and Reactivity

Stability	The product is stable
Possibility of Under normal conditions of storage and use, hazardous reactions will not occur	
hazardous reactions	
Conditions to avoid	Sources of ignition – heat, flames, sparks.
Incompatible materials	Strong acids and alkalis, oxidising agents.
Hazardous	Under normal conditions of storage and use, hazardous decomposition products
decomposition	should not be produced.
products	

## 11. Toxicological Information

Original data sourced from CCID and/or raw material SDSs:

Classification:	Skin Irritant – 6.3B	
Health Effects:	Causes mild skin irritation.	
Reference:	Derived by applying mixture rules	
Classification:	Eye Irritant – 6.4A	
Health Effects:	Causes serious eye irritation.	
Reference:	Derived by applying mixture rules	
Classification:	Skin Sensitiser – 6.5B	
Health Effects:	ealth Effects: May cause an allergic skin reaction	
Reference:	eference: Derived by applying mixture rules	

Date of issue: 7.12.18 NZ Safety Data Sheet

Classification:	Reproductive/Development Toxicant – 6.8B		
Health Effects:	Suspected of damaging fertility or the unborn child.		
Data:	Derived by applying mixture rules		
Classification:	STOT-RE - 6.9B		
Health Effects:	May cause damage to organs through prolonged or repeated		
	exposure.		
Reference:	Derived by applying mixture rules		
Acute Oral Toxicity	Does not trigger HSNO classification		
Acute Dermal Toxicity	Does not trigger HSNO classification		
Acute Inhalation Toxicity	Does not trigger HSNO classification		
Acute Aspiration Toxicity	Does not trigger HSNO classification		
Respiratory Sensitisation	Does not trigger HSNO classification		
Mutagenic	Does not trigger HSNO classification		
Carcinogenic	Does not trigger HSNO classification		
STOT-SE	Does not trigger HSNO classification		

### **Acute Toxicity Data**

**Product Acute Toxicity Estimate** 

ORAL LD50

>5000 mg/kg

DERMAL LD50

>5000 mg/kg

INHALATION LC50 (vapours)

>20 mg/L/4H

Product/Ingredient:	LD50 – Oral, mg/kg	LD50 – Dermal, mg/kg	LC50 – Inhalation, mg/L/4H
White Spirits - HF	3280 - Rat	-	18 – Vap - Rat
Gum Turpentine	5760 - Rat	-	12mg/L/6H - Rat
Xylene	1590 – Mouse	1100	27.6 – Vap – Rat

## 12. Ecological Information

This product is classified as Ecotoxic according to the criteria of HSNO.

H411 Toxic to aquatic life with long lasting effects.

**Ecotoxic Ingredients:** 

В
^
C
В
A
Ξ

Product Calculated Aquatic Ecotoxicity – L(E)C50 mg/L:
9.1B: >1 - ≤10
Ecotoxicity Data
White Spirits – HF (supplier's data)
Fish – Fathead minnow
_C50 7.72 mg/L / 96H
Crustacean – Cancer magister, Dungeness or edible crab
_C50 17 mg/L / 48H

Date of issue: 7.12.18 NZ Safety Data Sheet

Persistence & Degradability - Not available

**Mobility** - Not available

Bioaccumulation Potential - Not available

Other - Not available

### 13. Disposal Considerations.

Do not let this product enter the environment. Do not dispose of in waterways or sewers. Dispose of this material and its container as hazardous waste, via a licensed facility. See local council for disposal/recycling information.

#### 14. Transportation Information.

Regulated for transport Keep separated from foodstuffs

UN Number: 1263
Proper Shipping Name: PAINT
Class: 3
Packing Group: III
Hazchem: 3Y
Marine Pollutant: Yes

Land/Sea/Air EHSM also required for Sea/Air





### 15. Regulatory Information.

Group Standard: HSR002662

Surface Coatings & Colorants - Flammable

HSNO CONTROLS

SDS required when any quantity is present in a workplace.

At least 2 x 4.5kg powder fire extinguishers required when >500L is present in a workplace.

Emergency Response Plan and Secondary Containment required when >1000L is present in a workplace

Flammable signage required when >1000L is stored.

Ecotoxic signage required when >1000L is stored.

(Class 3.1C) Hazardous Substances	>500L (closed containers >5L)
Location Compliance Certificate	>1500L (closed containers up to 5L)
required for:	>250L (open containers)
(Class 3.1C) Hazardous Atmosphere	>100L (closed containers)
Zone required for:	>25L (decanting)
	>5L (open occasionally
	>1L (open containers in continuous use)
Certified Handler	Not Required
Tracking	Not Required

All ingredients are on the New Zealand Inventory of Chemicals (NZIoC), or exempt.

Any existing national regulations on the handling of dangerous substances should be observed. Controls for hazardous substances are based upon current knowledge. Where multiple chemicals are stored, controls will need to take into account aggregate quantities. Contact a WorkSafe approved Compliance Certifier for further information and guidance.

Date of issue: 7.12.18 NZ Safety Data Sheet

This material is not subject to the following agreements:

- Montreal Protocol (Ozone Depleting Substances)
- The Stockholm Convention (Persistent Organic Pollutants)
- The Rotterdam Convention (Prior Informed Consent)

### 16. Other Information.

HSNO = Hazardous Substances and New Organisms Act 1996.

EPA = Environmental Protection Authority

CCID = Chemical Classification and Information Database (EPA)

NZ WES = New Zealand Work Exposure Standard

TWA = Time Weighted Average

STEL = Short Term Exposure Limit

Date of SDS Preparation: 7 December 2018

The data given here is based on current knowledge and experience. The purpose of this Safety Data Sheet is to describe products in terms of their safety requirements. The above details do not imply any guarantee concerning composition, properties or performance of the product.